EMERGENCY PROCEDURES

1985 Cessna 182R N9438X

Bold-faced type are immediate action items which should be committed to memory.

Engine Failure During Takeoff

IVOII .		
1.	Throttle	Idle
2.	Brakes	Apply
3.	Wing Flaps	Retract
4.	Mixture	Idle Cut Off
5.	Ignition Switch	Off
6.	Master Switch	Off

Engine Failure Immediately After Takeoff 1. Airspeed

	75 KIAS (Flaps 70 KIAS (Flaps	Up)
2.	Mixture	Idle Cut Of
3.	Fuel Selector	O1

3.	Fuel Selector Off
4.	IgnitionOff
5.	Wing Flaps As Required
	(Full Recommended)
6.	Master SwitchOff

Engine Failure During Flight (Restart)

1.	Airspeed 75 KIAS	
2.	Carb HeatOn	
3.	Fuel SelectorBoth	
4.	MixtureRich	
5.	Ignition Both	
	(or START if propeller is	
	stopped)	
6.	PrimerIn & Locked	

Forced Landing w/o Engine Power

1.	Seat, Seat Belts,	Shoulder
	Harnesses	Secure
2.	Airspeed 7	75 KIAS (Flaps Up
	70 l	KIAS (Flaps Down
3.	Mixture	Idle Cut Of
4.	Fuel Selector	Of
5.	Ignition	Of
6.	Wing Flaps	. As Required (Fu
	Recommended)	
7.	Master Switch	Of
8.	Doors	Unlatch prior to
	Touchdown	
9.	Touchdown	Slightly Tail Lov
10). Brakes	Apply Heavily

Precautionary Landing With Engine Power

1. Seat, Seat Belts, Shoulder

	HarnessesSecure
2.	Airspeed75 KIAS
	Wing Flaps20°
	Select Field Perform
	Fly Over Inspection
5.	Electrical Switches Off
6.	FlapsFull on Final Approach
7.	Airspeed70 KIAS
8.	Avionics & Master Switches Off

Prior To Touchdo	wn
10. Touchdown	Slightly Tail Low
11. Ignition Switch	Off
12. Brakes	Apply Heavily

9. Doors......Unlatched

Engine Fire During Start

1.	Continue Cranking Engine	•
2.	If Engine Starts:	Po

2.	If Engine Starts:	. Power
	1700 RPM for a few minutes	

3.	Engine	Shutdown and Insp	ect
f E	Engine Fails	to Start:	

II Eligille Falls to Start	•
4. Throttle	Full Open
5. Mixture	•
6. Cranking	
7 Fire Extinguisher	

• •	i ii c Extiligatorici	
8.	Master/Ignition/Fu	uel Of
9	Fire	Extinguis

10. Fire Damage.....Inspect

Engine Fire in Flight

1	l. Mixture	Idle Cut Of
2	2. Fuel Selector	Of
3	B. Master Switch	Of
4	I. Cabin Heat & Air	Of
	(Except Overhead	Vents)
5	5. Airspeed	100 KIAS
	(If fire is not exting	

se glide speed to find an airspeed which will provide an incombustible mixture.)

6.	Forced Landing w/o Engine Power
	Execute

Electrical Fire in Flight

- 1. Master SwitchOff (Leave Ignition
- 2. Vents/Cabin Air/Heat Closed
- 3. Fire Extinguisher Activate

Warning After discharging an extinguisher within a closed cabin, ventilate the cabin.

4. Av	∕ionics Power Switch	Of
5. All	Other Switches (Except Ig	nitior
		Of
If fire	appears out and electrical	powe
is ned	cessary for continuance of	flight:
6. Ma	aster Switch	Or

7.	Circuit Breakers	Check fo
	Faulty circuit (Do No	t Reset)

- 8. Radio Switches Off
- 9. Avionics Power Switch...... On
- 10. Radio/Electrical Switches .. On one at a time w/ delay after each until short is localized.
- 11. Vents/Cabin Air/Heat Open when it is ascertained that fire is completely extinguished.

Cabin Fire

- 1. Master SwitchOff (Leave Ignition
- 2. Vents/Cabin Air/Heat..... Closed
- 3. Fire Extinguisher Activate

See Warning at Electrical Fire in Flight

4. Land...... As soon as possible and inspect damage

Wing Fire

1.	Pitot Heat	Of
	Navigation Lights	
	Strobe Lights	
	Landing/Taxi Lights	

Note

Sideslip to keep flames away from the fuel tank and cabin, and land as soon as possible using flaps only as required for final approach and touchdown.



Icina

- 1. Pitot Heat.....On
- 2. Turn back or change altitude to obtain an outside air temp that is less conducive to icing.
- Pull cabin heat control to full out and rotate defroster control clockwise to obtain maximum defroster airflow.
- 4. Increase Engine Speed to minimize ice build-up on propeller blades
- Watch for signs of carburetor air filter ice and apply carburetor heat as required. An unexplained loss of manifold pressure could be caused by carburetor ice or air intake filter ice. Lean the mixture if carburetor heat is used continuously.
- Plan a landing at the nearest airport. With an extremely rapid ice build-up, select a suitable "off airport" landing site.
- With ice accumulation of ¼ inch or more on the wing leading edges, be prepared for significantly higher stall speed.
- 8. Leave wing flaps retracted. With a severe ice build-up on the horizontal tail, the change in wing wake airflow direction caused by wing flap extension could result in a loss of elevator effectiveness.
- Open left window and if practical scrape ice from a portion of the windshield for visibility in landing approach.
- Perform landing approach using a forward slip, if necessary, for, improved visibility.
- 11. Approach at 80 to 90 KIAS depending upon the amount of accumulation.
- 12. Perform a landing in level attitude.

Ditching

- 1. Radio............ Transmit Mayday on 121.5 giving location and intentions and squawk 7700.
- 2. Heavy Objects..... Secure or Jettison.
- 3. Flaps...... 20° to 40°
- 4. Power Est. a 300 FPM descent at 65 KIAS.
- Approach
 High winds, heavy seas Into the Wind.
 Light winds, heavy swells............
 Parallel to swells.

Note

If no power is available, approach at 75 KIAS with flaps up or at 70 KIAS with 10° flaps.

- 6. Cabin DoorsUnlatch
- 7. Touchdown.....Level attitude at established descent rate.
- 8. Face Cushion at touchdown with folded coat.
- 9. Airplane Evacuate through Cabin doors. If necessary, open window and flood cabin to equalize pressure so doors can be opened.
- 10. Life vests and raft Inflate

For all other
Emergency
Abnormal
Procedures.
See the
POH
Section 3.

Airspeeds for Emergency Operations

Engine Failure After Takeoff:

Wing Flaps Up -- 75 KIAS Wing Flaps Down -- 70 KIAS

Maneuvering Speed:

3100 Lbs -- 111 KIAS 2600 Lbs -- 102 KIAS 2000 Lbs -- 88 KIAS

Maximum Glide:

3100 Lbs – 76 KIAS 2600 Lbs – 70 KIAS 2000 Lbs – 61 KIAS

Precautionary Landing With Engine Power – 70 KIAS

Landing Without Engine Power:

Wing Flaps Up - 75 KIAS Wing Flaps Down - 70 KIAS

This checklist is a guide to coordinate Pilot Operating Handbook and STC data applicable to this particular aircraft only. The applicable Pilot Operating Handbook and STC installations remain the official documentation for this aircraft.

The pilot in command is responsible for complying with all items in the Pilot Operating Handbook and applicable STCs.

I certify this checklist has been reviewed for accuracy.

//s// Col. Dalton Smith

01/20/2006

Wing Director of Maintenance

Date